

Software Error Notification

Pg. 1 of 2

Form 3.5.1 Revision: 2 Effective: 11/21/03

Error Notice Identification Nur Software Name: RA	DTRAD	Page <u>1</u>	of1
Versions Affected:	3.03	T. C.C. D.1. 1	
Error Classification: X S	Safety-Related N	Non Safety-Related	
Description of Error: The addition of offsite dose calculations to the control room dose calculation reduced the control room dose by a factor of 2.			
Assessment of error: This error may impact dose results. It may occur when the user defined time intervals for control room X/Q do not coincide with other time intervals form other time dependent input. A review of the problem indicated that the code does not use the time intervals from the control room atmospheric dilution input as part of its time step control.			
Software Program Manager:	Terry Heames Printed/Typed Name	Signature	
SW Point of Contact:	Terry Heames Printed/Typed Name	Signature	
Corrective Action: Option A: User should verify that any time intervals used to define control room X/Q were already included in other time dependent input. If not, insert all Control Room X/Q time values as other time dependent input, for example release from the containment could have multiple time values with the same time release pattern. The Appendix gives an example of the inclusion of the timing pattern. Option B: Modify code to include control room X/Q time intervals into the time step control routine. Because of the imminent release of version 3.10 a modification of version 3.03 is not considered reasonable. Verified Complete: Verified Complete:			
			QA Manager
Software Program Manager:	Terry Heames Printed/Typed Name	Signature	_ <u>July 22, 2004</u> Date
SW Point of Contact:	Terry Heames _ Printed/Typed Name	Signature	<u>July 22, 2004</u> Date



Software Error Notification

Form 3.5.1 Revision: 2

Effective: 11/21/03

Pg. 1 of 2

Appendix A: Sample Input Screens.

The Dose Location Screen shown below is taken from the error data deck. Note that the user has a 67 hour delay time and no dilution at time 0.0, then at about 3.5 seconds the dilution starts and over the next half hour changes several times before reaching a very low value. With a six minute time step the code thought there was no dilution for that first period because it had not included the time intervals into its time step control.

The Pathway Transfer Filters screen is shown with a full set of time intervals, even though the flow is constant. With this added input the time step control knows to take 3 second time steps and to get the start of the dilution, therefore changing the mass moved to the control room. The user should verify that the control room dilution time intervals are all included in another time dependent input.



